

Ultra Electronics CONTROLS 417 Bridport Road Greenford Middlesex UB6 8UE United Kingdom

Telephone: +44 (0) 20 8813 4444 Fax: +44 (0) 20 8813 4351

Email: support@ultra-controls.com

VENDOR SERVICE INFORMATION LETTER

STEERING DISCONNECT PANEL & MAINTAINABILITY PANEL

Part Numbers: 001SP0005 & 002MP0005

SUBJECT: STEERING DISCONNECT PANEL & MAINTAINABILITY PANEL –

SELECTIVE RECALL

ATA CHAPTER: 32

AIRCRAFT TYPE: Airbus A380

APPLICABILITY: Steering Disconnect Panel & Maintainability Panel

Part Numbers: 001SP0005 and 002MP0005

Serial Numbers: See Table 1

1. PURPOSE

This Vendor Service Information Letter is to provide Operators notice of a selective recall of the Steering Disconnect Panel, PNR: 001SP0005 and the Maintenance Panel PNR: 002MP0005.

2. BACKGROUND

A. Both the Steering Disconnect Panel (SP) and the Maintainability Panel (MP) contain a single Printed Circuit Board (PCB) as part of the overall assembly. The assembly drawings for these two boards state that the PCBs are to be conformal coated. It has been discovered during manufacture that on selective units the conformal coated has been not applied to the PCBs.

VSIL NUMBER: K8081-32-004

PAGE: 1 of 4 DATE: Jun 1/10



- B. Ultra Electronics Controls has reviewed the material and has identified where affected material was used and units installed.
- C. Airbus has recommended that the SP is replaced at the next available A Check and the MP is replaced at the next available C Check. However, when logistically possible where an Aircraft has both SP and MP affected Ultra Electronics Controls will endeavour to provide replacement units to enable replacement together.

3. **DESCRIPTION**

Information from Airbus showing the Aircraft with the affected panels is detailed in Table 1.

Operator - Air France					
A/C Registration	A/C Serial No.	Steering Panel Serial No.	Maintainability Panel Serial No.		
F-HPJA	033	001SP-2035	002MP-2033		
F-HPJB	040	001SP-2045	002MP-2016		
F-HPJC	043	N/A	002MP-2054		
Spare			002MP-2046		
Operator - Emirates					
A6-EDB	013	001SP-2025 (Note 1)	002MP-2019		
A6-EDC	016	N/A	002MP-2021		
A6-EDE	017	001SP-2039	002MP-2026		
A6-EDD	020	N/A	002MP-2013		
A6-EDG	023	N/A	002MP-2029		
A6-EDH	025	001SP-2033	002MP-2034		
Operator - Qantas					
VH-OQA	014	N/A	002MP-2015		
VH-OQB	015	001SP-2016 (Note 1)	002MP-2022		
VH-OQD	026	N/A	002MP-2009		
VH-OQE	027	001SP-2036	002MP-2024		
VH-OQF	029	001SP-2029	002MP-2036		

VSIL NUMBER: K8081-32-004

PAGE: 2 of 4 DATE: Jun 1/10



Operator – Singapore Airlines				
9V-SKC	006	N/A	002MP-2012	
9V-SKD	008	N/A	002MP-2023	
9V-SKE	010	N/A	002MP-2011	
9V-SKF	012	N/A	002MP-2017	
9V-SKG	019	001SP-2041	002MP-2045	
9V-SKH	021	001SP-2040	002MP-2020	
9V-SKI	034	001SP-2044	002MP2048	
9V-SKJ	045	N/A	002MP-2028	

Table 1 – Steering Disconnect Panels and Maintainability Panels

Note 1: SP serial numbers 001SP-2016 and 001SP-2025 are also subject to selective recall as detailed in VSIL: K8081-32-003.

4. ACTION

A. Operators in Table 1 are requested to contact Ultra Electronics – Controls to organise an exchange of each SP and MP. Ultra Electronics – Controls will make available a pool of spares to make sure the exchange is managed with the least inconvenience to Operators. The exchange of affected units will be carried out at no cost to Operators. The shipping address is:

Ultra Electronics CONTROLS 417 Bridport Road Greenford Middlesex UB6 8UE United Kingdom

- B. All Steering Disconnect Panels are to be returned complete with the Flag Pin Assembly (PNR: 001SP9000) as together they are a complete assembly. The SP and MP should be prepared for transportation as detailed in their respective ACMMs: 32-31-84 and 32-31-85.
- C. Operators are request to contact Ultra Electronics Controls before shipping any material. Operators can ship the panels to Ultra Electronics Controls using the following account:

FedEx Account Number: 149695443

VSIL NUMBER: K8081-32-004

PAGE: 3 of 4 DATE: Jun 1/10



5. **CONTACTS**

All queries relating to information contained in this Vendor Service Information Letter and to organise the exchange are to contact:

Julie Utton

Customer Account Executive (Aftermarket)

Telephone: +44 (0) 20 8813 4427 +44 (0) 20 8813 4351 Fax:

E-mail: julie.utton@ultra-controls.com

Danny Sharma **Customer Account Administrator**

Telephone: +44 (0) 20 8813 4726 Fax: +44 (0) 20 8813 4351 E-mail: danny.sharma@ultra-controls.com

VSIL NUMBER: K8081-32-004

PAGE: 4 of 4 DATE: Jun 1/10