

VENDOR SERVICE INFORMATION LETTER

Ultra Electronics CONTROLS 417 Bridport Road Greenford Middlesex UB6 8UE United Kingdom

Telephone: +44 (0) 20 8813 4444 Fax: +44 (0) 20 8813 4351

Email: support@ultra-controls.com

VENDOR SERVICE INFORMATION LETTER

SUBJECT: ICE AND RAIN PROTECTION

WING ICE PROTECTION SYSTEM

ZONE CONTROLLER

INTRODUCTION OF MODIFICATION "B"

ATA CHAPTER: 30-11

AIRCRAFT TYPE: Boeing 787 all variants

APPLICABILITY: Zone Controller

True Part Number: 003-CM-00-0200,

ATA Compliant Part Number: 003CM00-0200

REFERENCES: Component Maintenance Manual (CMM) 30-11-40

Ultra Electronics Controls Notice of Change: 003-CM-NOC-0029

1. PURPOSE

This Vendor Service Information Letter is to provide Operators notice of the introduction of Modification "B" which is being introduced as a minor change to Zone Controller, Part Number: 003-CM-00-0200.

Export of this technology is controlled under the United States Export Administration Regulations (EAR) (15 CFR 730-774). An export license may be required before it is used for development, production or use by foreign persons from specific countries. The controller of this data has the individual responsibility to abide by all export laws.

Export Control Classification Number: 9E991.

COPYRIGHT – The copyright in this document or any part thereof is the property of Ultra Electronics Ltd. © Ultra Electronics Ltd 2015
PROPRIETARY – This document and the information contained herein are the property of Ultra Electronics Limited. Recipient agrees to hold all such information in confidence and agree it shall be used only in accordance with applicable agreements and shall not be used for any other purpose. Recipient agrees not to disclose such information to any third party as provided for in agreements. Copying or disclosure by anyone without written permission is not authorised and may result in criminal and/or civil liability.

VSIL NUMBER: K8081-30-002

PAGE: 1 of 2 DATE: Dec 11/15



VENDOR SERVICE INFORMATION LETTER

2. BACKGROUND

Ultra Electronics Controls has identified that the Zone Controller Ground Fault Detection (GFD) peak voltage circuit in varying conditions is marginally failing the Acceptance Test Procedure during manufacture.

To counteract this marginal condition affecting the manufacture of the Zone Controller a change to increase the voltage gain of the GFD circuit is being introduced.

The Zone Controller remains Part Number: 003-CM-00-0200 with the change identified as Modification "B".

3. **DESCRIPTION**

The Zone Controller Resistor R441 value is changed from 10.2K to 13.7K Ohms to increase to voltage gain of the GFD circuit.

Information on the replacement specified parts will be detailed in the next revision of CMM 30-11-40.

4. SUPPORT INFORMATION

As the Zone Controller remains Part Number: 003-CM-00-0200 the pre-modified and post-modified Zone Controller is fully interchangeable and intermixable.

This change is implemented in July 2015 for all new Zone Controller Cards starting with serial number ZD503.

5. CONTACTS

All queries relating to information contained in this Vendor Service Information Letter contact:

Customer Support Manager at:

Ultra Electronics Controls 417 Bridport Road, Greenford, Middlesex UB6 8UE United Kingdom

Telephone: +44 (0) 20 8813 4444

Fax: +44 (0) 20 8813 4351

Email: support@ultra-controls.com

VSIL NUMBER: K8081-30-002

PAGE: 2 of 2 DATE: Dec 11/15