



VENDOR SERVICE INFORMATION LETTER

Ultra Electronics CONTROLS
417 Bridport Road
Greenford
Middlesex
UB6 8UE
United Kingdom

Telephone: +44 (0) 20 8813 4444
Fax: +44 (0) 20 8813 4351
Email: support@ultracontrols.aero

VENDOR SERVICE INFORMATION LETTER

LANDING GEAR CONTROL AND INTERFACE UNITs PART NUMBERS:

664700500A4A/B/C/D, 003LG034C & 005LG005B

SUBJECT: ULTRA ELECTRONICS CONTROLS - SINGAPORE REPAIR FACILITY

ATA CHAPTER: 32-31

AIRCRAFT TYPE: A318, A319, A320, A321, A330 & A340 Aircraft

APPLICABILITY: Landing Gear Control Interface Units (LGCIU) Pt. No. 664700500A4A/B/C/D, 003LG034C & 005LG005B.

REFERENCES: N/A

1. **PURPOSE**

This Vendor Service Information Letter is to inform Operators of changes to the Ultra Electronics Controls repair facility in Singapore.

2. **BACKGROUND**

Ultra Electronics Controls in liaison with TPA Pte Ltd provides Operators in the Asia/Pacific region with repair and spares support through a repair facility in Singapore.

VSIL NUMBER: K8081-32-001
PAGE: 1 of 2
DATE: May 30/07



VENDOR SERVICE INFORMATION LETTER

3. **DESCRIPTION**

In 2006 SATAIR A/S of Denmark acquired TPA Pte Ltd, and the integration of the activities of the two companies in Singapore is now complete. As of 1 April 2007 the name of the Ultra Electronics Controls repair facility will be SATAIR Pte Ltd. The contact details for SATAIR Pte Ltd are as follows:

Address:

SATAIR Pte Ltd
27 Loyang Way
Singapore 508728
Singapore

Phone: (65) 6543 0977

Fax: (65) 6543 0737

AOG: (65) 6543 0977

4. **ACTION**

All Operators to update their records detailing the new contact details for SATAIR Pte Ltd as the Ultra Electronics Controls repair facility in Singapore.